

# Kitemark<sup>®</sup> Licence

### No. KM 514540

The licence is granted to:

Pioneer Trading Company Essex Ltd Units 1-3 Red Barn, Warners Farm Howe Street Great Waltham Chelmsford CM3 1BN United Kingdom

In respect of:

### BS 7412/PAS24 Doors Fabricator

This issues the right and licence to use the Kitemark in accordance with the Kitemark Licence Conditions of Contract governing the use of the Kitemark, as may be updated from time to time by The British Standards Institution, and as approved by the Registrar under the Trade Marks Act 1994 (the "Conditions"). All defined terms in this Licence shall have the same meaning as in the Conditions.

The use of the Kitemark is authorized in respect of the Product(s) detailed on this Licence provided at or from the above address.

For and on behalf of BSI:

Gary Fenton, Global Assurance Director

First Issued: 30/07/2007 Latest Issue: 7/12/2012







# Kitemark<sup>®</sup> Licence

### No. KM 514540

BS 7412:2007 / PAS 24:2012 - General and enhanced security performance requirements for door assemblies

This Licence covers the fabrication of doors from the range of profiles and components supplied by Synseal Extrusions Limited under Licence Number KM 30983.

Synseal Extrusions Limited PVC-U Residential Door System

Fabricated and installed in accordance with the latest issue of the following Synseal Extrusions Limited manual(s):

Pioneer Trading Company Residential Door Manual Synseal Synerjy Technical Manual

#### System description:

The door assemblies are glaze in only with IGU(s) only, open in only, with midrails only, with standard threshold only and of fully welded construction.

## Synseal Synerjy PVC-U Residential Door System Size Limitations and Performance Characteristics

| Door Type                | Length (mm)<br>- Maximum | Height (mm) - Maximum (including sill) | Air Permeability classification | Watertightness<br>classification | Resistance to<br>Wind<br>classification | Exposure category<br>as given in Table 1<br>of BS 6375-1:2009 |
|--------------------------|--------------------------|--|---------------------------------|----------------------------------|---|---|
| Single leaf hinged doors | 900                      | 2100                                   | 2                               | 5A                               | A3                                      | 1200  |

<sup>\*</sup> Exposure category as given in Table 1 of PAS 23-1:1999

First Issued: 30/07/2007 Latest Issue: 7/12/2012

raising standards worldwide™

Page 2 of 3



This Licence remains the property of The British Standards Institution and shall be returned immediately upon request. To check its validity telephone +44 (0)845 080 9000



# Kitemark® Licence

### No. KM 514540

This Licence covers the fabrication of doors from the range of profiles and components supplied by Synseal Extrusions Limited under Licence Number KM 30983.

Synseal Shield PVC-U Residential Door System

Fabricated and installed in accordance with the latest issue of the following controlled manual(s):

Pioneer Trading Company Residential Door Manual

Synseal Shield Technical Manual

#### System description:

The door assemblies are glaze in only with IGU(s) only, open in only, with midrails only, with standard threshold only and of fully welded construction.

#### **Size Limitations and Performance Characteristics**

| Door Type                | Length (mm)<br>- Maximum | Height (mm)<br>- Maximum<br>(including sill) | Air Permeability<br>classification | Watertightness<br>classification | Resistance to<br>Wind<br>classification | Exposure category<br>as given in Table 1<br>of BS 6375-1:2009 |
|--------------------------|--------------------------|--|------------------------------------|----------------------------------|---|---|
| Single leaf hinged doors | 900                      | 2100   | 2                                  | 5A                               | А3                                      | 1200  |

<sup>\*</sup> Exposure category as given in Table 1 of PAS 23-1:1999

First Issued: 30/07/2007 Latest Issue: 7/12/2012



